

単位∶mm

記号	Z	Ш	規格
50×40	20	67	社内規格
65×50		80	AS 38
75 × 50	25	90	AS 38
75× 65		100	AS 38
100 × 50	30	105	AS 38
100 × 65		115	AS 38
100 × 75		120	AS 38
125 × 100	35	150	AS 38
150 × 100	40	170	AS 38
150 × 125		185	AS 38

備考 1. Zの許容差は、±2mmとする。2. Lは、基準寸法を示す。

図 名

VU IN 寸法図

東栄管機株式会社